

## VESA Plate Adaptors Installation Instructions

VESA plate adaptors (SAP-VESA-100-200, SAP-VESA-200-200, SAP-VESA-300-300 or SAP-VESA-400-400) require assembly in the field. Follow these installation instructions.

1. Place movement joint (A) with 100x100 VESA plate (B) against VESA plate adaptor (C) with Knoll logo toward the top, and align the holes.
2. Install the four (4) 8-32 screws (H) through the 100x100 VESA plate (B) and into the VESA plate adaptor (C).
3. Place VESA plate adaptor (C) against back of monitor (D) with Knoll logo toward top of monitor and align the holes.
4. Attach VESA plate adaptor (C) to monitor (D) using appropriate hardware (E) supplied by customer.
5. Mount monitor (D), now attached to the movement joint (A) to monitor arm (F) by inserting fast release pin (G).

### Tools Needed

Drive with 3/32" Allen tip

*Note: Consider size, pitch and length of screw when choosing hardware.*

*Spacers may be needed and can be ordered through Knoll Customer Service.*

