



Steps Ganging Installation Instructions

Reference Number: 6AJ9010

Tools Needed

Driver with Phillips bit #2

HARDWARE LIST	
<p>(A) x 2</p>  <p>P/N: 4AF3038 GANGING DEVICE SET (Ratchet and linear rack with teeth)</p>	<p>(B) x 20</p>  <p>P/N: 7399140 SCR - SM FLHD PHDR TYPE AB #10 x 3/4" BLACK OXIDE</p>

1. Lay steps on back surface.
2. Position steps adjacent to each other.
3. Position ratchet on 4th notch of linear rack with teeth. (Fig. 1)
4. Position bracket from joining edge and facing edge as indicated (Fig. 2). If joining multiple steps, fasten the ratchet sides of the ganging device sets to the same step.
5. Screw into place using driver.
6. Disconnect steps by lifting step with linear rack.
7. Carefully tip steps to standing position.
8. Adjust glides to level steps in position.
9. Reconnect ganging device by pushing pieces together, engaging the ratchet with the linear rack. To disengage, lift the step with ratchet, freeing it from teeth.

Fig 1




Fig 2

